

INTAKE MODULE ASSEMBLY
 Applicant: Murphy; Serial No. 10/644,440
 REPLACEMENT DRAWINGS



1/6




Fig-1

INTAKE MODULE ASSEMBLY
Applicant: Murphy; Serial No. 10/644,440
REPLACEMENT DRAWINGS

2/6




Fig-2A




Fig-2B

INTAKE MODULE ASSEMBLY
Applicant: Murphy; Serial No. 10/644,440
REPLACEMENT DRAWINGS

3/6




Fig-3A




Fig-3B

INTAKE MODULE ASSEMBLY
Applicant: Murphy; Serial No. 10/644,440
REPLACEMENT DRAWINGS

4/6




Fig-4




Fig-5

INTAKE MODULE ASSEMBLY
Applicant: Murphy; Serial No. 10/644,440
REPLACEMENT DRAWINGS

5/6




Fig-6

INTAKE MODULE ASSEMBLY
Applicant: Murphy; Serial No. 10/644,440
REPLACEMENT DRAWINGS

6/6

